



## Power On/Off

- Power On: Turn the ON/OFF knob clockwise (voice prompt will indicate remaining battery percentage)
- Power Off: Turn the ON/OFF knob counterclockwise until you hear a click

## Bluetooth Pairing

1. Enable Bluetooth on your device and search for “Wolf Apex BT”.
2. Select and pair. Once connected you will hear the voice prompt: “Bluetooth Connected.”
3. If the Bluetooth pairing fails within 2 minutes, a voice prompt “Pairing Failed” is heard.

Ensure your WOLF Apex BT and your device is within 20m distance of each other.

If the Bluetooth pairing fails within 2 minutes, a voice prompt “Pairing Failed” is heard.

## Entertainment (Bluetooth)

Operation	Action
Play / Pause music	Press the Menu button
Volume adjustment	Rotate the ON / OFF Knob
Next track	Press the Plus (+) button
Previous track	Press the Minus (-) button
Increase bass level	Press and hold the Plus (+) button for 1 second
Decrease bass level	Press and hold the Minus (-) button for 1 second

## Telephone

Operation	Action
Answer calls	Press the Menu button
End calls	Press the Menu button
Reject calls	Double press the Menu button
Switch between calls	Hold the Menu button for 2 seconds to accept an incoming call and place the 1 <sup>st</sup> call on hold (and vice versa)
Mute (mute on)	Press the Minus (-) button during a call
Unmute (mute off)	Press the Plus (+) button during a call

## Active Listening

Operation	Action
Active Listening (AL) levels	OFF - 25% - <b>50%</b> - 75% - 100%
Change AL levels	Double press the Menu button, then use the Plus (+) or Minus (-) buttons to increase or decrease the AL level

The headset will automatically revert to the previous AL level when powering on.

## Voice Control

Operation	Action
Activate Voice Control (Siri / Google Assistant)	Press and Hold the Menu button for 2 seconds

## Factory reset

Operation	Action
Factory Reset	Press and Hold the Plus (+) and Minus (-) buttons simultaneously for 3 seconds

Reset is complete when you hear the voice prompt: “Factory Reset Completed”